
Lighting and ADO Audit Report - Glendon goSAFE, VPFA



Date Completed: 2020-03-29 Run By:

| GLENDON CAMPUS | EXTERNAL LIGHTING | | | | | | | | |
|-----------------------|-------------------|----|-----|-----|-----------------------------|---|----|----|-----|
| Total Emergency: | 0 | of | 17 | out | Total City Lights: | 0 | of | 0 | out |
| Total Pot Lights: | 2 | of | 54 | out | ADO CHECKS | | | | |
| Total Wallpacks: | 0 | of | 69 | out | Total Exterior ADOs: | 0 | of | 40 | out |
| Total Street Lights: | 0 | of | 138 | out | Total Interior ADOs: | 0 | of | 21 | out |
| Grand Total Out: | 2 | of | 368 | out | | | | | |



Lighting and ADO Audit Report - Glendon goSAFE, VPFA

| Date Con | npleted: 2020-03-29 | Run By: | | |
|------------|---------------------|----------------------------------|---------------|---|
| ADO-Ext | | | SubTotal Out: | 0 |
| ID | Area | Description | | |
| Zone (If A | Applicable): | | | |
| ADOEXT999 | 9 MASTER | Ignore - master list placeholder | | |